

Nordic Thingy:91 v1.0.0

Errata

v1.0

2 Change log

Version	Date	Change
Nordic Thingy:91 v1.0.0	17.1.2020	<ul style="list-style-type: none">Added: No. 1. "Low antenna efficiency on GPS frequencies"

1.0: Low antenna efficiency on GPS frequencies

This anomaly applies to Nordic Thingy:91 v1.0.0

Symptoms

Marginal GPS performance using on-board antenna.

Conditions

Using the GPS with on-board antenna.

Consequences

It will, in most conditions, take a long time to get a GPS fix with the on-board antenna.

Workaround

Connect an external active GPS antenna with needed power supply to the switched antenna connector in the GPS signal path.