



【Precaution】

When a board with multiple connectors mounted is mated, the connector may be damaged or deformed.
Please divide one side of the board so only one connector is mated per board.

OK



NG



HRS	DRAWING NO.	EDC-150565-71-25
	PART NO.	FX8-90P-SV(71)
	CODE NO.	CL578-0004-4-71
		1 2 2