




1. place adhesive pad  
on board holder




2. ENSURE PROPER ORIENTATION  
BEFORE REMOVING ADHESIVE.  
PLACE ADHESIVE BOARD  
HOLDER INTO BASE, WITH THE  
ARROW TOUCHING THE WALL.



4. INSTALL COVER





5. INSTALL CLEAR  
COVER PLATE





3. PLACE BOARD AND  
INSTALL SCREWS.


Recommended PCB screw torque  
28.0-35.5 ozf-in (20-25 cN-m)



6. INSTALL DIN RAIL CLIP



Dimensions:  
mm  
[inches]



HAMMOND  
MANUFACTURING.  
INSTRUCTIONS  
1597KITS  
[www.hammondmfg.com](http://www.hammondmfg.com)