



Micron Semiconductor Products, Inc.  
8000 S Federal Way  
P.O. Box 6  
Boise, Idaho 83707-0006  
Telephone: 208-368-4000  
Fax: 208-368-2536

Dear Valued Customer,

We would like to inform you that effective April 2019, Micron will be establishing a +/-3% Quantity Tolerance Policy related to our Die Wafer products.

Purchase orders placed to Micron for Die Wafer parts will now have a standard tolerance rule to adjust and ship +/-3% of the original order quantity, unless a specific quantity tolerance guideline is stated.

Following each shipment, Micron's automatic shipment notifications or invoice sent via email or EDI will indicate the quantity (within -3% to 3%) that was shipped, to specify the adjustments made.

To avoid unexpected delays in receiving product or invoicing issues, please take note of the new policy moving forward and send this notification to all appropriate individuals.

If you can accept a quantity tolerance that is less or more than the Micron +/-3% standard, please provide your requirement to your local Micron Sales Operations Specialist so we capture your requirement.

For questions or concerns, please contact your local Micron Sales Operations Specialist.

Thank you,

8000 S Federal Way  
P.O. Box 6  
Boise, Idaho 83707-0006  
Telephone: 208-368-4000  
Fax: 208-368-2536