

Thermal Sensor Handling Guide

1. Purpose of the Guide

The purpose is to eliminate characteristic degradation and fracture defect of the product which occurs at logistic process due to static electricity or being contaminated by hand contact.

2. Instruction

- (1) Keep the humidity between 40 to 70%.
- (2) Use conductive or cotton type for gloves and finger cot.
- (3) Wear a wrist strap on the either right or left hand.
- (4) Put a conductive sheet (1×105 to $1 \times 109 \Omega$) on the working table and connect to ground with the resistance of $1M\Omega$.
- (5) Hold the edge of a board so as not to touch the wiring, electric parts ,and the surface of the lens.

