






Träger mit Buchseneinsätze
Montage Reihenfolge

The diagram illustrates the assembly sequence for a carrier with bush inserts. It consists of two main parts: a perspective view of the carrier and an exploded view of the carrier with a bush insert. The perspective view shows the carrier with three numbered callouts: 1 points to the top of the carrier, 2 points to the bottom of the carrier, and 3 points to the side of the carrier. The exploded view shows the carrier with a bush insert being inserted into the top. An arrow points from the perspective view to the exploded view.

LEVER IN LOCKED POSITION
Hebel in Verriegelungsstellung

[illegible]

1	TYCO ELECTRONICS (TE) LOGO AND TE NUMBER Tyco Electronics (TE) Logo und TE Nummer	8	BULK PACKAGING IN CORRUGATED BOX Schüttgut im Versandkarton
2	FITS TO TE RECEPTACLE INSERT AMP MCP 1.5K 18 POSITION, 1718489-1 Passend zu TE Buchseineinsatz AMP MCP 1.5K 18 polig., 1718489-1	9	FITS TO TE COUNTERPART 1.5/2.8 MM TAB HOUSING, 18-7POS 1718491 / 2112890 Passend zu TE Gegenstecker 1.5/2.8 mm Flachsteckergeh., 18-7pol., 1718491 / 2112890
3	FITS TO TE RECEPTACLE INSERT AMP MCP 2.8 7 POSITION, 1718488-1 Passend zu TE Buchseineinsatz AMP MCP 2.8 7 polig., 1718488-1	10	MALFUNCTION CAUSED BY LACQUER IS NOT COVERED BY TE WARRANTY Funktionsbeeinträchtigung durch Lackieren liegt nicht im Einfluss und Gewährleistungsumfang von TE
4	PRODUCTION DATE Produktionsdatum	11	FITS TO TE INTERFACE DRAWING 11A-18721 Passend zu TE Ausführungsverschrift 11A-18721
5	MATERIAL IDENTIFICATION ACC TO VDA 260 Werkstoffkennzeichnung nach VDA 260	A3 12	CARRIER MATERIAL MARKING ACCORDING TO MATERIAL SOURCE Träger werkstoffkennzeichnung gem. d. B. werkstoffquelle
6	WARPAGE TO . . . PERMITTED Verzug zulässig bis . . .		
7	CODING MARKING Kodierungskennzeichnung		

